


Ramond  
Box 76  
Baltimore



ATT: DWAYNE J. WHITE  
PATENT EXAMINER  
ART UNIT 3745

USPTO  
CUSTOMER SERVICE WINDOW,  
RANDOLPH BUILDING,  
401 DULANY STREET,  
ALEXANDRIA, VA 22314.  
COMMISSIONER OF PATENTS  
P.O. BOX 1450,  
ALEXANDRIA VA 22313,  
PHONE (571) 272-482



163745

USA.

10/804-709

ATT: DWAYNE J. WHITE  
PATENT EXAMINER  
ART UNIT 3745

USPTO  
CUSTOMER SERVICE WINDOW,  
RANDOLPH BUILDING,  
401 DULANY STREET,  
ALEXANDRIA, VA 22314.  
COMMISSIONER OF PATENTS  
P.O BOX 1450,  
ALEXANDRIA VA 22313,  
PHONE (571) 272-4825



Charles Raymond,  
Inventor  
Ph/Fax: (679) 667 8078  
Appl No. 10/804/709  
Dated: 25 - 10 - 05

USPTO  
Customer Service Window,  
Randolph Building,  
401 Dulany Street,  
Alexandria VA 22314.

Commissioner of Patent,  
P.O.Box 1450,  
Alexandria VA 22313.

**Examiner Art Unit 3745**  
**ATT - Dwayne J. White**  
Ph: (571) 272 4825

RECEIVED  
NOV 02 2005  
TECHNOLOGY CENTER R3700

Dear Mr. White,


Thank you for your patient guidance in this case. I have tried to follow your advice and am submitting a response to your first office action.

I apologize for not being more familiar with the correct terminology used by a patent attorney.

I have again put a claim that is generic, and it is followed by a dependent claim which could replace the generic claim if the generic claim won't fly. I couldn't see why the cited art would preclude allowing the claim however.

Again, the easiest way to reach me for clarification or required changes is by email [raymond@connect.com.fj](mailto:raymond@connect.com.fj).

Thank you,



Charles Raymond

Transmittal

29 pages (Including address) of response

5 Pages of Photograph

Photos

- (A) Fig 6A shows pump intakes  
Top shows intake, hole for shaft  
Bottom shows concave housing with  
two intakes into plenum area  
Fig 6A is in drawings
- (B) Fig 1A shows direct coupled pump  
Bottom shows jet stream.  
Fig 1A is in drawings
- (C) Shows parts of pump in Fig 1A  
tangential vane entry
- (D) shows hydromotor  
Top foto shows two tangential  
intakes similar to Fig 6A  
Bottom foto shows rotor with  
tangential vanes at rotor periphery
- (E) shows hydromotor with only  
one side hooked up to show how  
fluid goes straight through pump.  
Rotor is turning 2750 rpm